

# Building Fitness Certificate

**FITNESS CERTIFICATE**  
To be filled by the Inspecting Officer (Asst. Engineer)  
(Re: G.O. Ms. 20/70/PWD Dt. 23-01-1970)

1. Name of the Officer: Remya M  
 2. Name of the School: Chinthalya Vidyalaya Senior Secondary  
 3. Location with name of Education District/ Sub-District: Devancode, Kallikadu, Nayyarthipuram  
 4. Classification of Building as specified in column 4 of the application for fitness certificate and size: Details of Building Attached

5. Period for which the certificate is issued: 2020-21

6. Nature of defects, if any:  
 a) Foundation and basement: \_\_\_\_\_  
 b) Superstructure: \_\_\_\_\_  
 c) Doors and Windows: \_\_\_\_\_  
 d) Wood work wrought and put up: \_\_\_\_\_  
 e) Roof: \_\_\_\_\_  
 f) Flooring: \_\_\_\_\_  
 g) Miscellaneous (Cracks, etc.): Nil

7. Any major defects noticed which will render the building unsafe in any manner: Nil

8. Whether maintenance works have been done properly: Yes

9. Whether the structure is sound or not for conducting classes: Structure is safe to conduct classes

**Note:** 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished formally separately with this certificate.

**CERTIFICATE**

certified that the school building was inspected by me on 01/01/2021 and found to be fit / unfit to conduct classes, for the period 2020-21 for the reasons stated above.

Place: Kallikadu  
 Date: 06.01.2021

Assistant Engineer  
 LGD (P) SECTION  
 KALLIKADU SECTION  
 NAYYARTHIPURAM

Classification of the Building and size (basis for classification) (See annexure I): Main Block (Permanent Multi storeyed) (fitness certificate obtained)  
Permanent Single or multi storeyed

**Permanent building**  
RCC Cellular Durium (North & South)  
 1. 14.70 x 6.20 x 3.20 North  
 2. 14.70 x 6.20 x 3.20 South  
**RCC Ground Floor**  
 (All Measurements shown are in metres)  
 1. 14.70 x 6.20 x 3.20 North  
 2. 14.70 x 6.20 x 3.20 South  
 3. 6.20 x 6.40 x 3.20 North & South  
 4. (4.70 + 8.40) / 2 + 6.20 x 3.20 (do)  
 5. 24.90 x 6.20 x 3.20 North & South  
 6. (4.30 + 4.50) / 2 x 6.20 x 3.20 (do)  
 7. 3.90 x 4.70 x 3.20 North & South  
 8. 6.20 x 6.20 x 3.20 North & South  
**RCC First Floor**  
 1. 14.70 x 6.20 x 3.20 North  
 2. 14.70 x 6.20 x 3.20 South  
 3. 6.20 x 6.40 x 3.20 North & South  
 4. (4.70 + 8.40) / 2 + 6.20 x 3.20 (do)  
 5. 24.90 x 6.20 x 3.20 (do)  
 6. (4.30 + 4.50) / 2 x 6.20 x 3.20 (do)  
 7. 3.90 x 4.70 x 3.20 North & South  
 8. 6.20 x 6.20 x 3.20 (do)  
**Aluminium Sheet Roofing (Second Floor)**  
 1. 14.70 x 6.20 x 3.20 North  
 2. 14.70 x 6.20 x 3.20 South  
 3. 6.20 x 6.40 x 3.20 North & South  
 4. (4.70 + 8.40) / 2 + 6.20 x 3.20 (do)  
 5. 24.90 x 6.20 x 3.20  
 6. (4.30 + 4.50) / 2 x 6.20 x 3.20 (do)  
 7. 3.90 x 4.70 x 3.20 North & South  
 8. 6.20 x 6.20 x 3.20

**Science Block (Permanent Multi storeyed) (fitness certificate obtained)**  
 1. 31.78 x 19.21 x 3.30 (Ground Floor)  
 2. 31.78 x 19.21 x 3.30 (First Floor)

**Nursery Building (old) (Semi Permanent sheet roofing) (fitness certificate obtained) (converted to open auditorium)**  
 Total 332.74 m.sq.

**New Nursery Building (Permanent multi storeyed)**  
**Size of Building**  
**Ground Floor**  
 1. Plinth Area : 442 sq.m.  
 2. Head Room : 18sq.m.  
 3. Courtyard : 43 sq.m.  
**Total** 535 sq.m.  
**First Floor**  
 1. Plinth Area : 442 sq.m.  
 2. Courtyard : 43 sq.m.  
**Total** 485 sq.m.

Assistant Engineer  
 LGD (P) SECTION  
 KALLIKADU SECTION  
 NAYYARTHIPURAM



*[Signature]*  
**MANAGER**  
 Chinthalya Vidyalaya  
 Senior Secondary School  
 Devancode, Kallikadu